## RECOVERED SECTION CORNER

SEC. 94
NW COR. SEC. 93

DESCRIPTION: NW COR, SEC. 93, T35, Rlw, EAST FELICIANA PARISH. (COMMON TO SECS. 42 , 94)

FOUND: STEEL GRATE BAR STICKING OUT OF GROUND
18" ON 04/13/00.

REPORTED: BY DARREL PRIMEAUX, P.L.S.

## LOUISIANA DIVISION OF ADMINISTRATION STATE LAND OFFICE

## Public Land Survey Monument Recovery Record Please use a separate form for each recovered monument

CORNER DESCRITION:  Northwest corner of Section 93, Township 35outh, Range / west
Louisiana Meridian or _/St. Helena Meridian in East Feliciana Parish, Louisiana
Original Monument FoundLocally Accepted Monument FoundMonument Set
List all sections adjacent to this monument.  42
94
Description of original monument and accessories and subsequent restoration ( <i>if known</i> ). Give sources of information.
MONUMENT DESCRIPTION: Description of monument and accessories if found:
Steel grate bar sticking out of ground 18" on 4/13/00.
Common to Secs. 42/94
Description of monument and accessories if set:
Louisiana State Plane Coordinates of Corner (if determined):  X:Y:
Zone: Datum: Coordinates Determined From: GPS Survey
Conventional Survey

SKETCH		
1		
REFERENCE MEASUREMEN	NTS (at least three):	
Description	Distance	Bearing (Give Basis)

IF MONUMENT WAS SET, METHOD USED TO DETERMIE LOCATION OF LOST CORNER.

SUBMITTED BY: <u>Darre / Primeaux</u>, <u>PL</u>S (please print)

DATE: 3-15-2001

Submit To:

Louisiana State Land Office

P.O. Box 44124

Baton Rouge, LA 70804-4124

SLO database registration No. NW593-735-RIW-E

NOTE:

The information contained heron was submitted by the above named Surveyor on a voluntary basis. The State Land Office does not certify that the monument described hereon marks the actual corner it is intended to represent. This information is included in a database that should be used as a research tool only.